

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	0	200/5.ccls.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:01
S3	2439	200/13,14,18.ccls.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:02
S4	2290	S3 and @pd<"20002010"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:03
S7	4	S4 and (pressure) and (monitor) and (switch)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:11
S9	262	S4 and (pressure) and (switch)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:12
S10	353	200/43.01,50.01.ccls.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:23
S11	247	S10 and @pd<"20002010"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:23

S12	6	"716127".ap.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:28
S13	2	"5421829".pn.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:32
S15	1303	(switch) same (pressure with monitor\$3) and (time with delay)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:55
S16	67	S15 and hysteresis and sensor	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:57
S17	6	S16 and ultrasonic	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 12:58
S18	42	S16 and @pd<"20002010"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/02 13:00
S19	279	433/118.ccls.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/07 12:48
S20	216	S19 and @pd<"20002010"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/07 12:48

S21	0	S20 and (monitore\$2 with pressure)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/07 12:49
S22	67	S20 and ( pressure)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/07 12:49
S23	6	"716127".ap.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/07 13:06
S24	2	"6945981".pn.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/07 13:18
S25	0	("6945981").URPN.	USPAT	OR	OFF	2009/07/07 13:20
S26	23	("2917691"   "4321530"   "4979952"   "5001649"   "5026387"   "5060658"   "5112300"   "5180363"   "5400267"   "5425704"   "5449370"   "5630420"   "5707369"   "5879364"   "5968007"   "6013048"   "6017354"   "6019775"   "6037724"   "6066135"   "6090123"   "6252334").PN.	US_PGPUB; USPAT; USOCR	OR	OFF	2009/07/07 13:20
S27	2	"6013048".pn.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/07 14:05
S28	2	"4979952".pn.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/07 14:06

S29	85	"4934934"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/07 14:23
S30	2	"4934934".pn.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/07 14:24
S31	2	"5514140".pn.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/07 14:24
S32	2	"5421829".pn.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 15:35
S33	616	(ultrasonic with surgical) same (handpiece)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 15:40
S34	198	S33 and @pd<"20001020"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 15:42
S35	60	S34 and switch	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 15:42
S36	4	S35 and (pressure with sensor)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 15:43

S37	3544	(response near4 time) and (delay) same (sensor) and (switch)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 16:36
S38	4	S37 and handpiece and vibrate	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/07/09 16:37

7/ 10/ 2009 11:40:03 AM

C:\ Documents and Settings\vnguyen10\ My Documents\ EAST\ Workspaces\ 10716127.wsp